

## 98-050 FERROGRAPH Tape Recorder Test Set RTS 2 (FOR SPARES/REPAIRS)



### 98-050 FERROGRAPH Tape Recorder Test Set RTS 2 (FOR SPARES/REPAIRS) – UNIT 1

For Spares and Repair – Main in put via IEC connector

Fault: No d/p on 10db, 0db onwards.

Millivoltmeter switch also suspect

IEC mains cable required (not supplied) e.g.:-

42-3186 AC MAINS POWER CORDSET IEC C13 female - UK 13A, 3 metres, black

42-3190 AC MAINS POWER CORDSET IEC C13 female - UK 13A, 5 metres, black

**CANFORD**



www.canford.co.uk

## 98-050 FERROGRAPH Tape Recorder Test Set RTS 2 (FOR SPARES/REPAIRS)



### 98-050 FERROGRAPH Tape Recorder Test Set RTS 2 (FOR SPARES/REPAIRS) – UNIT 3

For Spares and Repair – Main in put via IEC connector  
Fault: No d/p on 10db, 0db onwards.  
Millivoltmeter switch also suspect  
Screws for top and bottom panel missing

IEC mains cable required (not supplied) e.g:-

42-3186 AC MAINS POWER CORDSET IEC C13 female - UK 13A, 3 metres, black

42-3190 AC MAINS POWER CORDSET IEC C13 female - UK 13A, 5 metres, black

**CANFORD**



[www.canford.co.uk](http://www.canford.co.uk)